

Computer Science 773

Robotics and Real-time Control

NUMERICALLY CONTROLLED TOOLS

EXAMPLE OF A MILLING SEQUENCE.

(G.Stute and H.Eitel : *The milling technology in Exapt 3*, in W.H.P.Leslie (Ed) :
NC Programming Languages (North-Holland, 1970))

THE PART TO BE CONSTRUCTED :

THE MILLING SEQUENCE :

First :


Second :

Third :

Fourth :

EXAMPLE OF A PROGRAMME IN 2C,L.
 (D.G. Wilkinson : *Cam manufacture*, in W.H.P.Leslie (Ed) :
NC Programming Languages (North-Holland, 1970))

THE SYSTEM AND SOME VARIABLES :



THE PROGRAMME :

```

PARTNO C205 CAM. (D-R-D-R-O)
REMARK CAM HAS A ROLLER FOLLOWER MOUNTED ON A RADIUS ARM.
REMARK D.G. WILKINSON N.E.L. X5 17-12-68.
CLPRNT

REMARK INPUT VARIABLES FOLLOW.
XCENT = 3.5 $$ X DISTANCE FROM CENTRE OF CAM TO CENTRE OF PIVOT.
YCENT = 3.026 $$ Y DISTANCE FROM CENTRE OF CAM TO CENTRE OF PIVOT.
STRTRD = 2.053 $$ BASE RADIUS OF CAM.
FOLDIA = 1.084 $$ DIAMETER OF FOLLOWER
RADARM = 3.55 $$ LENGTH OF RADIUS ARM.
LMAX = 16 $$ MAXIMUM ANGULAR TRAVEL OF RADIUS ARM.
ALFA1 = 24 $$ STARTING ANGLE OF FIRST LIST PERIOD.
THETA1 = 60 $$ ANGLE OF FIRST LIFT PERIOD.
ALFA2 = 108 $$ STARTING ANGLE OF SECOND LIST PERIOD.
THETA2 = 195 $$ ANGLE OF SECOND LIFT PERIOD.

REMARK CUTTING VARIABLES FOLLOW.
CUTDIA = 1 $$ CUTTER DIA. IN INCHES.
SPEED1 = 400 $$ SPINDLE SPEED IN RPM.
RAPID1 = 15 $$ RAPID FEED RATE ( INS/MIN).
ROF1 = 5 $$ ROUGHING FEED RATE ( INS/MIN).
FIN1 = 1 $$ FINISHING FEED RATE ( INS/MIN).
    
```

```

REMARK    STATIC GEOMETRY CALCULATIONS.
DIAG      = SQRT(XCENT**2+YCENT**2) $$ RADIAL DISTANCE TO PIVOT.
TWOPI    = 3.14159 *2
TEMP1    = RADARM**2+DIAG**2 $$ B**2 + C**2 USED IN COSINE FORMULA.
TEMP2    = 2*RADARM*DIAG      $$ 2*B*C IN COSINE FORMULA.
MINDST   = STRTD+FOLDIA/2 $$ MINIMAL RADIAL DISTANCE TO FOLLOWER CENTRE.
ANG1     = ATAN(YCENT/XCENT) $$ ANGLE OF PIVOT FROM POS. X-AXIS.
ANG2     = ACOS((TEMP1-MINDST**2)/TEMP2) $$ MIN. ANGLE BETWEEN
          $$ RADARM AND DIAG,
MAXDST   = SQRT( TEMP1-TEMP2*COS(ANG2+LMAX)) $$ MAX. RADIUS
          $$ TO FOLLOWER CENTRE.
ENDRAD   = MAXDST-FOLDIA/2 $$ MAXIMUM CAM RADIUS.
          PRINT/3,DIAG,MINDST,ANG1,ANG2,MAXDST,ENDRAD

REMARK    INITIALIZE VARIABLES.
THETA    = 0          $$ CUMULATIVE CAM LIFT ANGLE.
GAMMA1   = ALFA1+ANG1-2 $$ CUMULATIVE ANGLE OF PIVOT FROM POS. X-AXIS.
GAMMA2   = ANG2       $$ CUMULATIVE ANGLE BETWEEN RADARM AND DIAG.
DELTA1   = THETA1/8   $$ 8 INCREMENTS ALONG LIFT CURVE.
THETAT   = THETA1     $$ TOTAL CAM LIFT ANGLE.

REMARK    GEOMETRY MACRO FOR DEFINING CENTRE OF FOLLOWER (PQ).
MACQ1    = MACRO/PQ
RADQ     = SQRT(TEMP1-TEMO2*COS(GAMMA2)) $$ RADIUS TO CENTRE OF FOLLOWER.
GAMMA3   = ASIN(SIN(GAMMA2)*RADARM/RADQ) $$ ANGLE BETWEEN PIVOT AND FOLLOWER.
PQ       = POINT/ORIG,THETAR,(GAMMA1+GAMMA3),RADQ
          TERMAC

REMARK    LIFT FUNCTION MACRO.
MACQ2    = MACRO/
LIFT     = LMAX*(THETA/THETAT-SIN(TEMP3*THETA)/TWOPI) $$ LIFT ANGLE OF
          TERMAC                                     $$ RADIUS ARM.

REMARK    CALLING MACRO FOR LIFT PERIOD.
MACQ3    = MACRO/PQ1
          CALL/MACQ1,PQ=PQ1  $$ DEFINE POINT PQ.
THETA    = THETA+DELTA1     $$ INCREMENT CAM LIFT ANGLE.
          CALL/MACQ2        $$ CALCULATE LIFT ANGLE OF RADIUS ARM.
GAMMA1   = GAMMA1+ABS(DELTA1) $$ INCREMENT ANGLE OF PIVOT.
GAMMA2   = ANG2+LIFT        $$ INCREMENT ANGLE BETWEEN RADARM AND DIAG.
          TERMAC

REMARK    MACRO TO DEFINE FOLLOWER CURVE AND CAM PROFILE.
MACQ4    = MACRO/TABQ1,LQ1,LQ2,LQ3
TEMP3    = 360/THETAT $$ USED IN LIFT FUNCTION.
          CALL/MACQ1,PQ=P1  $$ DEFINE P1 AND P2 AT CONSTANT RADIUS.
          GAMMA1=GAMMA1+1  $$ SPACED AT 1 DEGREE INCREMENTS BEFORE
          CALL/MACQ1,PQ=P2  $$ START OF LIFT PERIOD TO GIVE CONTINUITY
          GAMMA1=GAMMA1+1  $$ OF LIFT CURVE.
          CALL/MACQ3,PQ1=P3
          CALL/MACQ3,PQ1=P4
          CALL/MACQ3,PQ1=P5
          CALL/MACQ3,PQ1=P6
          CALL/MACQ3,PQ1=P7
          CALL/MACQ3,PQ1=P8
          CALL/MACQ3,PQ1=P9
          CALL/MACQ3,PQ1=P10
          CALL/MACQ1,PQ=P11
          GAMMA1=GAMMA1+1
          CALL/MACQ1,PQ=P12
          GAMMA1=GAMMA1+1
          CALL/MACQ1,PQ=P13
TABQ     = TABCYL/NOZ,SPLINE,P1,P2,P3,P4,P5,P6,P7,P8,P9,P10,P11,P12,P13
TABQ1    = TABCYL/PARLEL,LEFT,TABQ,(FOLDIA/2)
LQ1     = LINE/ORIG,P3

```

```

LQ2    = LINE/ORIG,P11
LQ3    = LINE/ORIG,P7
        TERMAC

REMARK  DEFIND CAM PROFILE FOR PERIOD LIFT1.
ORIG    = POINT/0,0 $$ CENTRE OF CAM.
        CALL/MACQ4,TABQ1=LIFT1,LQ1=L1,LQ2=L2,LQ3=L1A

REMARK  DEFINE LINE GEOMETRY FOR START AND END OF CUT.
PCENT   = POINT/ORIG,THETAR,(GAMM1+GAMMA3-2),(ENDRAD+CUTDIA*2)
BLEND   = CIRCLE/CENTRE,PCENT,RADIUS,(CUTDIA/2)
STRTLN  = LINE/PCENT,PERPTO,L2

REMARK  RESET VARIABLES FOR SECOND LIFT PERIOD.
THETA   = THETA2
GAMMA1  = ALFA2+ANG1-2
GAMMA2  = ANG2+LMAX
DELTA1  = -THETA2/8 $$ GIVES NEGATIVE INCREMENTS.
THETAT  = THETA2

REMARK  DEFINE CAM PROFILE FOR PERIOD LIFT2.
        CALL/MACQ4,TABQ1=LIFT2,LQ1=L3,LQ2=L4,LQ3=L3A

REMARK  DEFINE REST OF GEOMETRY.
C1      = CIRCLE/0,0,STRTRD $$ BASE CIRCLE OF CAM.
C2      = CIRCLE/0,0,ENDRAD $$ MAX. CAM RADIUS CIRCLE.
SETPNT  = POINT/0,0,3 $$ SET POINT 3 INCHES ABOVE CAM CENTRE.

REMARK  MACRO FOR CUTTING ONCE ROUND THE CAM.
MACQ5   = MACRO/FEED1
        CUTTER/KUT
        GO/ON,STRTLN,(PLANE/0,0,1,3),ON,L2,RAPID1
        GODLTA/-3
        AUTOPS
        GORGT/STRTLN,TO,BLEND
        TLRGT
        GORGT/BLEND,ON,L2,FEED1
        GOFWD/C2,ON,L3
        GOFWD/LIFT2,ON,L3A
        GOFWD/LIFT2,ON,L4
        GOFWD/C1,ON,L1
        GOFWD/LIFT1,ON,L1A
        GOFWD/LIFT1,ON,L2
        GOFWD/BLEND,ON,STRTLN
        GODLTA/3,RAPID1
        GOTO/SETPNT
        TERMAC

        SPINDL/SPEED1
PPRINT  ROUGH OUT CAM .02 INCH OVERSIZE.
        FROM/SETPNT
        INTOL/.005
        OUTTOL/.005
KUT     = CUTDIA+.04
        CALL/MACQ5,FEED1=RUF1
        STOP
        SPINDL/SPEED1
PPRINT  FINISH CAM.
        INTOL/.00005
        OUTTOL/.00005
KUT     = CUTDIA
        CALL/MACQ5,FEED1=FIN1
        END
        FINI

```

THE VALUE OF NUMERICAL CONTROL.

(P. Fiorellino : *Introductory course in the numerical control of machine tools*
(ACIERA, 1980).)

Comparing manual control with numerical control; economy of scale.

Advantage of a "high-level" language.

DESCENDANTS OF NUMERICAL CONTROL.

(P. Fiorellino : *Introductory course in the numerical control of machine tools*
 (ACIERA, 1980).)

	Degree of integration	
Automated machining	Automated machining sequence	Automated manufacturing sequence
Includes Machining with - positioning - measuring NC M	Includes Machining with - positioning - measuring tool exchange	Includes Machining with - positioning - measuring tool exchange Workpiece change Storage and transfer - workpiece (-tools)
NC MC (machining centers)		Total control -flow of information - flow of material
NC MC (FMS) (flexible manufacturing systems)		

Alan Creak,
 March, 1998.